

- ★ READ CAREFULLY THIS INSTRUCTION MANUAL AND THE INSTRUCTIONS OF THE HOT AIR PROBE (MODEL SF-40), EACH OF GAS DETECTOR TUBES AND ASPIRATING PUMP (MODEL AP-20) PRIOR TO USE OF THIS PRODUCT.
- ★ ENSURE THAT THIS INSTRUCTION MANUAL IS STORED IN A CONVENIENT LOCATION SO THAT YOU CAN REFER AT ANYTIME.
- ★ NEVER USE THE MODEL SFH-01 HOT AIR PROBE HOLDER FOR ANY PURPOSES OTHER THAN STATED USE.

1. PREFACE

This Product is used for fixation of the hot air probe (Model SF-40), a gas detector tubes and the aspirating pump (AP-20). The stability of the hot air probe is enhanced with the hot air probe holder.

▲ CAUTION

1. A TOP OF THE HOT AIR PROBE RUNS HOT AFTER MEASUREMENT. TO AVOID INJURY, ALLOW ADEQUATE COOLING TIME.
2. KEEP THE PRODUCT OUT OF THE REACH OF CHILDREN.

NOTICE

1. USE ONLY WITH THE HOT AIR PROBE (SF-40) AND THE GAS ASPIRATING PUMP (AP-20).
2. PRIOR TO USE, READ CAREFULLY ITEM 5. USER RESPONSIBILITY.

2. SPECIFICATION




Fig.1

3. OPERATION




Fig.2

- ① Remove the rubber tube holder from the detector tube connecting part of an aspirating pump and connect the holder screw of the hot air probe holder.
- ② Break both ends of a detector tube and insert it into the connecting tube of the hot air probe securely.

▲ CAUTION

SAFETY GLASSES AND GLOVES SHOULD BE WORN TO PREVENT INJURY FROM SPLINTERING GLASS.

- ③ Insert the detector tube and hot air probe through the insertion hole of the hot air probe holder as shown in Fig.2, then insert the detector tube into the rubber tube connector securely (Arrow mark of detector tube shall point to the pump).
- ④ Turn the Screw knob and fix the Hot air probe firmly.

4. DISPOSAL OF PRODUCTS:

USED TUBES, HOT AIR PROBE AND HOT AIR PROBE HOLDER SHOULD BE DISPOSED CAREFULLY ACCORDING TO RELEVANT REGULATIONS, IF ANY.

5. USER RESPONSIBILITY:

It is the sole responsibility of the user of this equipment to ensure that the equipment is operated, maintained and repaired in strict accordance with these instructions and the instructions provided with Model AP-20 and Hot Air Probe (Model SF-40) and each of Gas Detector Tubes. The Manufacturer and Manufacturer's Distributors shall not be otherwise liable for any incorrect measurement or any damages, whether damages result from negligence or otherwise.

IME39142

Printed in Japan

